

## Table of Contents

Preface .....	2
Table of Contents.....	3
List of Figures .....	6
I. Description of Site.....	8
A. Wood Island .....	8
Names .....	8
Location.....	8
Geology .....	8
Vegetation.....	9
Current Use .....	9
B. Existing Structures and Infrastructure .....	9
1. Wood Island Station.....	9
The Origins of Lifesaving in the Region.....	10
Structure's History .....	11
Historical & Cultural Significance.....	11
Conditions Assessment .....	13
Exterior.....	13
Interior .....	14
2. Tool House Building .....	18
Conditions Assessment .....	18
3. Marine Railway .....	18
Structure's History .....	19
Conditions Assessment .....	20

# Wood Island Feasibility Study

August 2008

4. Seawall .....	21
Conditions Assessment .....	22
South Seawall.....	22
North Seawall.....	23
5. Flag Tower.....	24
Conditions Assessment .....	24
6. Drill Pole .....	24
Structure's History .....	24
Conditions Assessment .....	25
7. Well.....	25
8. Miscellaneous Facilities.....	25
9. Cribs .....	28
Conditions Assessment .....	29
II. Town of Kittery Stewardship.....	30
A. History of Ownership.....	30
B. Biennial Compliance Reports.....	31
C. Past Concepts and Proposals .....	34
D. Past Grant Applications: .....	37
E. Other Lifesaving Stations & Developed Sites.....	38
Resource List .....	41
Places and Organizations .....	41
Individuals (In Order of Chronological Appearance).....	42
Appendix A.....	45
Chronology of Historical Events & Correspondences pertaining to Wood Island Site .....	45

Wood Island Feasibility Study

---

August 2008

Appendix B .....	62
Building Drawings & Damage Summaries:.....	62
Appendix C .....	63
Related Documents:.....	63

## List of Figures

Figure 1: Wood Island .....	8
Figure 2 Wood Island Station.....	9
Figure 3 Jerry's Point Lifeboat Station .....	10
Figure 4 Lifeboat Men at Jenness Beach.....	11
Figure 5 View of Whaleback Lighthouse and Wood Island Station .....	12
Figure 6 Collapsed station roof.....	13
Figure 7 Wood Island Station.....	14
Figure 8 Interior damage of boathouse .....	15
Figure 9 Non-structural interior damage.....	15
Figure 10 Seagull droppings.....	16
Figure 11 Station foundations.....	16
Figure 12 Fibrous pipe insulation.....	17
Figure 13 Stairs and peeling paint.....	17
Figure 14 Tool House Building .....	18
Figure 15 Launching the Thomas Fielden .....	19
Figure 16 Marine Railway .....	20
Figure 17 Seawall .....	21
Figure 18 Outer south seawall.....	22
Figure 19 Damaged top section of south seawall.....	22
Figure 20 Inner north seawall damage .....	23
Figure 21 Outer north seawall damage .....	24
Figure 22 Beach apparatus drill reenactment in Cape Cod .....	24
Figure 23 Overgrowth.....	26

## Wood Island Feasibility Study

---

August 2008

Figure 24 Abandoned tanks .....	26
Figure 25 Manhole .....	27
Figure 26 Piping.....	27
Figure 27 Cribs .....	28
Figure 28 Cribs near Wood Island .....	29
Figure 29 Former Biddeford Pool USCG Station .....	38
Figure 30 Former Biddeford Pool USCG Station .....	39
Figure 31 Wood Island Light Station .....	39
Figure 32 Wallis Sands State Beach .....	40